

### **SAS Superstructure**

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 347 Const Calendar Day: 803 Date: 16-Aug-2014 Saturday Inspector Name: Liu, Tai-Lin Title: Transportation Engineer

Inspection Type: Continuous

**Shift Hours:** 06:00 AM 02:30 PM **Break:** 00:30 **Over Time:** 08:00

Federal ID: Location:

Reviewer: Awal, Mohammad Approved Date: 13-Sep-14 Status: Approved

Weather

 Temperature
 7 AM
 60 - 70
 12 PM
 70 - 80
 4PM
 70 - 80

 Precipitation
 Condition
 Clear

Working Day 🗸 If no, explain:

Diary:

#### tower Activites

CCO # 382 - Tower Painting and Cleaning works (8/16/14, Saturday - Clear):

- \* Performed paper work, and checked e-mail. Went to job site (T1 base by boat) around 09:15 AM.
- \* At tower base (footing & El.13m), did not see ABF's labore there. Saw CCC painter Edilberto performing paint repair on south side of tower, El. 33m to 18m façade area (see picture). He finished out the painting work by using single swing stage, another painter Luis Ventura helping him got out the stage and went up to tower above El. 53 m. From tower base footing, saw two L-shape swing stages with 6 painters continued performing paint repair on N/W shafts D/C faces at El. 53m & 77 m respectively. US hoist personel was not in El. 13 area, but in El.53m working on tower elevator.
- \* After lunch, drove to W2 and walked to Tower entance EI.53. Saw two L-shape swing stages with 6 painters continued performed paint repair on N/W shafts, D/C faces at EI. Close to 53m (below 53m). At tower EI. 53m near elevator entrance, saw ABF forman James and two IRWs Obra polk & Johnathan working on steel walkway (see picture). Two painters (Armando & Manuel) performed paint repair on S/E shafts A face at EI. 53m area. No ABF's labore work in tower today.
- \* Saw METS paint inspector Stuart at the area between tower shafts façade walking area. Talked to him, he mensioned that he finished checking on south side of tower from El.53 m down to El.18 m; he also said that at El. 38m in SE/SW corner area need to be caulking. Also he did check paint repair from El. 53m to El. 65m at E face N/W shafts area. Talked to QC Sage, he told me that total 12 painters on the tower paint repair work today.
- \* Only James worked today. No ABF's labor work today.
- \* Paint Crew: Sage Ray, Armado Avitia, Manuel Ramirez, Cory Reese, Alberto Serrano, Juan Carlos, Luis Ventura, Oscar Salazar, Ramon Gutierrez, Edilberto Leno, Daniel Rosales, Abraham Ventura. Crew worked from 6AM to 2:30 PM, 8 hours shift.

04-0120F4	Bid Item: 0	53 T-L01-DSE.053	Tower Lift 01 Diaphram Tower SE Erect structural steel (bridge tower)									
AMERICAN BRIDGE/FLUOR, A JV												
Labor												
Trade	Class	Name	RT Hrs OT Hrs DT Hrs Total Remarks Dispute									
Contractor:	AMERICAN BRIDG	GE/FLUOR, A JV										
Ironworker	JNM	DONALD PLUMB	0.00 0.00 0.00 0.00									
Ironworker	JNM	PAUL FAMBRINI	0.00 0.00 0.00 0.00									



Run date 22-Nov-14

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Time 11:34 AM

		_	iry Report by Bia item						
ob Name: 04-012	20F4 Insp	ector Name: Liu, Tai-Lin		Dia	ry #: <sup>34</sup>	7 Date	e: 16-Aug-2014	Saturday	
Semi-Skilled Lab	oorer JNM	FERMIN MEDINA	0.00	0.00	0.00	0.00			
Ironworker	GEN	AARON KENT	0.00	0.00	0.00	0.00			
Semi-Skilled Lab	oorer JNM	LUIS Jimenez	0.00	0.00	0.00	0.00			
Semi-Skilled Lab	oorer JNM	DANNY SCHWARTZ	0.00	0.00	0.00	0.00			
Semi-Skilled Lab	oorer APP	JAVIER MEDINA	0.00	0.00	0.00	0.00			
Semi-Skilled Lab	oorer FOR	GUILLERMO LIMON	0.00	0.00	0.00	0.00			
Semi-Skilled Lab	oorer APP	ROGELIO RODRIGUEZ	0.00	0.00	0.00	0.00			
Semi-Skilled Lab	oorer JNM	CARLOS MONTEJANO	0.00	0.00	0.00	0.00			
Semi-Skilled Lab		JOSE AVILA	0.00	0.00	0.00	0.00			
Semi-Skilled Lab	oorer JNM	VICTOR HERNANDEZ	0.00	0.00	0.00	0.00			
Ironworker	FOR	JAMES STURGEON	0.00	0.00	0.00	0.00			
Equipment						Re	ntal Company		
Equipment ID	Description		RT Hrs (	OT Hrs	ST Hrs	IT Hrs Re	marks	D	ispute
Contractor: AME	ERICAN BRIDGE	E/FLUOR, A JV							
*E0020562	WELDING E	EQUIPMENT					No		
			0.00	0.00	0.00	0.00			
*E0030562	WELDING E	EQUIPMENT				1	No		
			0.00	0.00	0.00	0.00			
*E0010562	WELDING E	QUIPMENT				ļ	No		
			0.00	0.00	0.00	0.00			
2292	WELDER, 6	00 AMP					No		
			0.00	0.00	0.00	0.00			
2293	WELDER, 6	00 AMP	0.00	0.00	0.00	0.00	No		_
04-0120F4	Bid Item: 07	'8 T-L01-ENE.078	Tower Lift 0	11 Evtor	nal Pain	t Tower N	F		
CERTIFIED COATIN			TOWER LINE	/ LALGI	iiai i aiii	t TOWEI IN	_		
04-0120F4	Bid Item: 07	78 T-L05-ENE.078	Tower Lift 0	5 Exter	nal Pain	t Tower N	E		
CERTIFIED COATIN	IGS COMPAN	Υ							
04-0120F4	Bid Item: 07	'8 T-HEA-ENE.078	Tower Head	Extern	al Paint	Tower NE			
CERTIFIED COATIN	IGS COMPAN	Υ							
	Bid Item: 00		CIC - Elevat	tor Impa	acts - US	A Hoist			
AMERICAN BRIDGE	FLUOR, A JV								

#### Attachment



Job Name: 04-0120F4 Inspector Name: Liu, Tai-Lin Diary #: 347 Date: 16-Aug-2014 Saturday



Took boat to T1 around 9:10 AM



CCC three painters at swing stage performed paint repair at N shaft



CCC three painters performed paint repair on L-shape swing stage on W shaft D/C faces El. 50m



CCC painter Armando performed paint repair on E shaft A face at El. 53 m




Painters were leaving swing stages on north side of tower at end of shaft




Two painters on swing stage El. 77 m between W & S shafts performed paint repair

Job Name: 04-0120F4 Inspector Name: Liu, Tai-Lin Diary #: 347 Date: 16-Aug-2014 Saturday



Three CCC painters performed paint repair on N shaft D/C faces EI. 53m area




Painter - Edilberto continued painting façade area on south side of tower




Painter Luis came down to El.18m area helping Edilberto to get out the stage



CCC painter Manuel performed paint repair on S shaft face A El. 53m




Painters on L-shape swing stages were leaving from north of tower



METS inspector Stuart was leaving tower El. 53m at the end of the shaft

Job Name: 04-0120F4 Inspector Name: Liu, Tai-Lin Diary #: 347 Date: 16-Aug-2014 Saturday



James, Obra & Johnathan (ABF) worked on steel walkway near elevator at El. 53m



Saw two swing stages with 6 painters on N/W shafts D/C faces at EI.53m & 77m areas